

PARTS FOR ACCORDIONS HIGH VELOCITY

LONG BUSHING SHORT BUSHING HAT




AL = ALUMINUM S.S. = STAINLESS STEEL, HWS = HEX WASHER HEAD, Z = ZINC
 HEX = HEXAGONAL

LEGEND: ' = FEET

" = INCHES

CONVERT INCHES TO DECIMALS

1" = 1.0, 3/4" = .75, 1/2" = .50, 1/4" = .25, 1/8" = .125



COMMON FASTENERS

TE SCREWS



STORM PANELS

